

KILLED!

TRUCK FALLS **OFF LIFT**



David S., a 46-year-old mechanic, was killed when a truck he was repairing fell off a lift. The truck was too long, and so the arms of the lift did not reach the proper lift points. David's employer did not have safety or training programs.

WHAT WENT WRONG?	WHAT SHOULD BE DONE?
The wrong type of lift was used.	Only use lifts that can support a vehicle at the points designated by the vehicle manufacturer.
There was no safety program to make sure workers used lifts correctly.	Employers should have an Illness and Injury Prevention Program (IIPP) to make sure workers are fully trained and follow safe work practices.

For complete fatality reports of this case (03CA10) or other cases, and information on the California Fatality Assessment and Control Evaluation (FACE) Program, contact:

California Department of Health Services Occupational Health Branch, FACE Program 1515 Clay Street, Suite 1901, Oakland, CA 94612 or visit our website at www.dhs.ca.gov/ohb/ohsep/face.

To obtain a copy of this document in an alternate format, please contact: OHB at (510) 622-4300

or CA Relay Service at (800) 735-2929

Please allow at least ten working days to coordinate alternate format services.





JULY 2004

Sandra Shewry, Director Health and Human Services Agency Kimberly Belshé, Secretary State of California Arnold Schwarzenegger, Governor

Department of Health Services

the National Institute for Occupational Safety Occupational Health Branch and funded by California Department of Health Services, FACE is a public health program run by the and employees can help prevent them. cause work-related deaths so that employers the FACE Program is to find problems that may and Control Evaluation." The purpose of FACE stands for "Fatality Assessment

and Health.

California Department of Health Services Occupational Health Branch, FACE Program 1515 Clay Street, Suite 1901 Oakland, CA 94612

PLEASE POST